

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2063	DATE	July 16, 2014
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	Some of these motorcycles may have been assembled with a front brake line in a position where it could become pinched between the fuel tank and the frame, either at original assembly or in subsequent service activity. If this condition remains undetected it could cause front brake fluid pressure to increase while riding, possibly resulting in a front wheel lock-up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FLHM	STREET GLIDE	2014 (MY)	997
EBL-FLHL	ULTRA LIMITED	2014 (MY)	416
EBL-FLHM	ROAD KING CLASSIC	2014 (MY)	243
EBL-FLHL	ELECTRA GLIDE URTRA CLASSIC	2014 (MY)	228
TEN	CVO™ LIMITED	2014 (MY)	194
PG8	CVO™ ROAD KING	2014 (MY)	140
		TOTAL	2218