

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | Gai-2061 | DATE | July 16, 2014 |
| MANUFACTURE | Automobiles PEUGEOT Automobiles CITROËN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.) | | |
| DESCRIPTION OF DEFECT | The front suspension wishbone mounting bolts might not have been manufactured to the correct specification potentially causing a risk of these parts breaking. Broken mounting bolts can be noticed by the driver through noises and poor directional control. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|-----------------|---------------------|-------------------|
| ABA-A94HM01 | PEUGEOT 2008 | 2013 | 147 |
| ABA-A95F01 | PEUGEOT 208 | 2013 | 106 |
| ABA-A9CHM01 | PEUGEOT 208 | 2013 | 83 |
| ABA-A9HM01 | PEUGEOT 208 | 2013 | 468 |
| ABA-A55F01 | CITROEN C3 | 2013 | 137 |
| ABA-A5C5F01 | CITROEN DS3 | 2013 | 82 |
| ABA-A5C5F02 | CITROEN DS3 | 2013 | 79 |
| ABA-A5CHM01 | CITROEN DS3 | 2014 | 46 |
| ABA-A5HM01 | CITROEN C3 | 2013 | 100 |
| | | TOTAL | 1248 |