

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2092	DATE	Sep. 25. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has been notified by tyre supplier Continental Reifen Deutschland GmbH to the effect that with the tyre types listed below, in isolated cases tread separation can occur, resulting in loss of inflation pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S1000RR	BMW S1000RR	2010 – 2014	1,656
K1300S	BMW K1300S	2009 – 2010	308
EBL-K13AA	BMW K1300S	2011 – 2014	344
K1300R	BMW K1300R	2009 – 2010	228
EBL-K13AA	BMW K1300R	2011 – 2014	284
		TOTAL	2,820