

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2069	DATE	Sep 18, 2014
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2014 model year Chevrolet Camaro and Impala vehicles. Some of these vehicles may have fasteners that are not torqued to specifications at the interface of the intermediate shaft and the steering gear and/or at the lower control arm to the lower ball joint. If these fasteners are improperly torqued, they could back out and the vehicle could exhibit loss of steering and lead to a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
——	「CAMARO」	2014	1
		TOTAL	1