

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2087	DATE	Sep 10 th 2014
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag. In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-3E44	ALPINA B3-3.3	1999 – 2000	95
GF-3E46	ALPINA B3-3.3	2001 – 2002	119
GF-3E48	ALPINA B3-3.3 4WD Touring	2002	7
GH-3E48	ALPINA B3-3.3 4WD Toruing	2002 – 2004	18
GF-3E48	ALPINA B3-3.3 4WD	2002 – 2003	4
GH-3E48	ALPINA B3-3.3 4WD	2004 – 2005	3
GH-3E50	ALPINA B3S	2003 – 2005	127
	ALPINA B3S Coupe	2003 – 2006	36
	ALPINA B3S Touring	2002 – 2004	18
	ALPINA B3S Cabrio	2003 – 2006	18
GH-3E51	ALPINA B3S	2003 – 2005	24
	ALPINA B3S Coupe	2003 – 2006	5
	ALPINA B3S Touring	2002 – 2004	3
	ALPINA B3S Cabrio	2003 – 2006	6
		TOTAL	483