

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2117	DATE	20 Nov 2014
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The engine will either not start or if already running normally, may loose ignition to one cylinder (casued by excessive fuelling), leading to a liss of engine power, resulting loss of driving force and momentum.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-7J865	Bonneville	2014	5
	Bonneville T100	2014	9
	Thruxton	2014	4
EBL-7J865S	Scrambler	2014	4
EBL-BJ800	Tiger 800 XC ABS	2014	4
		TOTAL	26