

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2113	DATE	November 14, 2014
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a temporary manufacturing error, there is a possibility that front lid lock upper parts, on which the catch bar was not riveted to the mounting plate according to specifications, were installed on the affected vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-981MA122	Boxster	2014	17
	Cayman	2015	9
ABA-981MA123	Boxster S	2015	1
	Cayman S	2015	10
ABA-991MA103	911 Carrera S	2014, 2015	13
	911 Carrera S Cabriolet	2014	1
	911 Carrera 4S	2014, 2015	8
	911 Carrera 4S Cabriolet	2014	1
	911 Targa 4S	2014	1
ABA-991MA104	911 Carrera	2014, 2015	19
	911 Carrera Cabriolet	2014	3
	911 Carrera 4	2015	2
ABA-991MA171	911 Turbo	2014, 2015	7
	911 Turbo S	2014, 2015	17
		TOTAL	109