

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2125	DATE	Dec 11, 2014
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided to conduct a Voluntary Emission Recall involving certain 2014 model year Cadillac ATS vehicles. Some of these vehicles have a condition in which the electrical terminals are not properly crimped to the Accelerator Pedal Position (APP) circuits at the engine harness side of an inline electrical connector. If this occurs, Diagnostic Trouble Code (DTC) P2138 may set as a result of the associated high resistance, causing both traction and stability control systems to be disabled, reduced engine power mode operation, and the Malfunction Indicator Lamp (MIL) to illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A1SL	「ATS」	2014	59
		TOTAL	59