VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	3490	DATE	December 18 ,2014
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF			
DEFECT	Some semi-trailers with 3 axles which are for 40 feet oversea container, do not have enough strength of the stay of a side bumper for an inappropriate shape. If it will be used continuously, a crack may occur in the stay and it would break the stay.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NCCTB34081	—	2011~2013	232
NTCTB34081	—	2011~2013	3
		TOTAL	235