

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2130	DATE	2014/12/25
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	In wet weather condition, due to the water dip on the brake booster, the brake booster shell may prematurely corrode. If perforation of the brake booster shell occurs, the driver may be required to apply additional application force to apply the brakes. An unexpected additional brake pedal application force requirement could slow the driver's brake application reaction time and cause a crash without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-WK36	Jeep Grand Cherokee	2011-2012	1, 756
ABA-WK36A	Jeep Grand Cherokee	2011-2012	1, 145
ABA-WK36T	Jeep Grand Cherokee	2014	115
ABA-WK36TA	Jeep Grand Cherokee	2014	106
ABA-WK57A	Jeep Grand Cherokee	2012-2013	140
-WK57A-	Jeep Grand Cherokee	2013-2014	183
Total			3, 445