

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2135	DATE	Jan 7, 2015
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	Certain model year 2015 TRI GLIDE ULTRA models (FLHTCUTG) have a Rear Brake Master Cylinder that may have been assembled at the supplier with an incorrect piston, which does not provide proper support to the primary cup (seal). This could allow a tear to develop in the primary cup.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-TGL	TRI GLIDE ULTRA	2015 (MY)	229
		TOTAL	229