

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2147	DATE	Mar. 12, 2015
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in all 2003-2010 model year (MY) Cadillac CTS, 2011 MY Cadillac CTS (VIN D and Built Prior to December 13, 2010) and 2004-2006 MY Cadillac SRX vehicles. If the key ring is carrying added weight and the vehicle goes off road or experiences some other jarring event, it may unintentionally move the key away from the "run" position. If this occurs, engine power, power steering and power braking will be affected, increasing the risk of a crash. If the ignition switch is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury or fatality.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「GF-AK64K」	「Deville」	2000 - 2002	825
「GH-AK64K」		2003 - 2005	217
「GH-X272」	「DTS」	2006 - 2007	163
「ABA-X272」		2008 - 2009	60
「-X272-」		2010	20
「GH-AD32F」	「CTS」	2003 - 2004	176
「GH-AD33G」			119

「GH-AD32G」	「CTS」	2005 - 2007	74
「GH-AD33H」			75
「ABA-X322A」		2008	3
「ABA-X322C」		2010 - 2011	161
「GH-T265E」	「SRX」	2004 - 2006	166
「GH-T265S」		2005 - 2006	72
		TOTAL	2131