

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2199	DATE	2015/6/30
MANUFACTURER	FCA US LLC ( Japanese Importer : FCA Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	The Totally Integrated Power Module (TIPM) of the vehicles concerned contains an internal fuel pump relay that could operate intermittently or fail without warning. An intermittent or failed fuel pump relay could cause the engine to stall while driving and cause a crash without warning		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-WK36	Jeep Grand Cherokee	2011	259
ABA-WK36A	Jeep Grand Cherokee	2011	126
Total			385