

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2193	DATE	5 June 2015
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	The rear suspension unit on certain Triumph Daytona 675R ABS and Speed Triple R ABS models has a possible assembly defect. The piston-shaft nut has in some cases not been torqued correctly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HB	DAYTONA 675 R ABS	2014–2015	37
NX	SPEED TRIPLE R ABS	2015	10
EBL–5J1050			1
		TOTAL	48