VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestie / Import Vehicles

CAMPAIGN No.	Gai - 2210	DATE	July 22, 2015	
MANUFACTURER	KTM Sportmotorcycle GmbH			
	(Japanese Importer : KTM Japan KK)			
DESCRIPTION OF DEFECT	In some fuel tanks, two threaded inserts which secure the internal overflow			
	pipe on the inside may not be completely enclosed on the outside of them.			
	It can lead to fuel lead	king. In worst case, the lea	ked fuel would cause fire	
	accident.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
1290SDV3949	「1290SUPERDUKE R」	2014	138 UNITS
		TOTAL	138 UNITS