

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2204	DATE	July.17, 2015
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	SAFETY RECALL: Certain 2013 Model Year Mustang 3.7L Vehicles - PCM Reprogram Certain left hand drives Mustang vehicles built in Flat Rock between 12 October 2011 and 26 September 2012. On affected vehicles the Electronic Throttle Control Failure Mode and Effects Management strategy, when active, prevents illumination of the "Check Engine" light on the next driving cycle as required by On-Board Diagnostic regulation. Dealers are required to reprogram for Power train control module.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Mustang	2013	14 units
TOTAL			14 units