

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|--|------|----------|
| CAMPAIGN No. | Gai-2198 | DATE | 2015/7/2 |
| MANUFACTURE | Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | <p>On smart fortwo (451 platform) vehicles the fixation bolts of the steering gear on the front cross member might have been manufactured outside specification. This is due to a deviation at a supplier.</p> <p>Because of the temporary deviation from the specification, a fixation bolt could break and vehicle handling could be affected. In case a fixation bolt breaks, the general steering function is still available with a broken screw. The driver will be alerted to the issue e.g. by perceptible noises and affected driving handling.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|---------------------|---------------------|-------------------|
| ABA-451380 | Fortwo coupe | 2014 | 247 |
| | | 2015 | |
| CBA-451332 | Fortwo coupe turbo | 2014 | 5 |
| CBA-451432 | Fortwo cabrio turbo | 2014 | 12 |
| | | 2015 | |
| ZAA-451390 | Fortwo coupe EV | 2015 | 205 |
| | | TOTAL | 469 |