

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2220	DATE	16.10. 2015
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	SAFETY RECALL: Certain 2005-2006 Ford GT and 2005-2008 Mustang Vehicles. - Airbag inflator Replacement Certain 2005-2006 Ford GT and 2005-2008 Mustang Vehicles. Ford Motor Company North America has been requested to take this action by the National Highway Traffic Safety Administration. Dealers are to replace the driver airbag inflator and return the original inflator for analysis. This service must be performed on all affected vehicles at no charge to the vehicle owner.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
	Mustang	2007	412 units
TOTAL			412 units