

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3675	DATE	November 11, 2015
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	With regard to the lashing equipment of semi-trailers, since the fabrication control of recessed rope hooks was inappropriate, some welds of the hooks and stoppers were half-done. For this reason, if the trailers are used in the present state, vibrations during driving or some other movement can lead to separation of the hooks and stoppers welded, which loosens the hooks, leaving a risk that loads may fall off while in motion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPFH241AN	Semi Trailer	2015	1
DFPFH341A	Semi Trailer	2015	2
DFPTF241AN	Semi Trailer	2015	1
DFPFH341AN (Modified)	Semi Trailer	2015	1
Total			5