

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3731	DATE	December 25, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, when the airbag inflates, the container of inflator may be broken, components may be scattered due to abnormal rise in internal pressure of the inflator, causing passengers to be injured		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GG3P UA-GG3P	Mazda 「ATENZA」	2002 - 2005	1,402
LA-GG3S UA-GG3S		2002 - 2005	7,792
LA-GY3W UA-GY3W		2002 - 2005	11,392
LA-GGEP UA-GGEP		2002 - 2005	1,945
LA-GGES UA-GGES		2002 - 2005	928
LA-GYEW UA-GYEW		2002 - 2005	1,200
		Total	