

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2280	DATE	18.Dec.2015
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	Due to the possible production defect on the low pressure fuel line connection of the fuel pump feed pipe which were fitted, there is the possibility of the small fuel vapor leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142B	488GTB	2015	7
ABA-F149DD	California T	2015	1
		TOTAL	8