

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2306	DATE	January 29, 2016
MANUFACTURER	FCA US LLC ( Japanese Importer : FCA Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	The Totally Integrated Power Module (TIPM) of the vehicles concerned contains an internal fuel pump relay that could operate intermittently or fail without warning. An intermittent or failed fuel pump relay could cause the engine to stall while driving and cause a crash without warning		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-WK36	Jeep Grand Cherokee	2012MY-2013MY	1,511
ABA-WK36A	Jeep Grand Cherokee	2012MY-2013MY	1,034
ABA-WK57A	Jeep Grand Cherokee	2012MY-2013MY	140
-WK57A-	Jeep Grand Cherokee	2012MY-2013MY	170
Total			2,855