

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2313	DATE	2016/2/25
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Daimler AG determined that during a workshop visit, a pre-production ESP software has been installed onto the ESP control unit of certain CLA (117 platform), A- (176 platform) and B-class (246 platform) vehicles instead of the approved series software due to an error in the documentation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-176042	A180	2013	1
		2014	8
DBA-176044	A250	2014	1
DBA-246242	B180	2013	2
		2014	1
DBA-117342	CLA180	2014	2
DBA-117346	CLA250 4MATIC	2014	2
		TOTAL	17