

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3771	DATE	Feb. 18 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty, regular-service, CNG-powered buses, the front fog light indicator showing the illumination of the front fog lights is not installed because of the improper drawing for the electrical wiring.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-MP37JK KAI	「FUSO AERO STAR」	2006~2006	13
KL-MP37JM KAI		2006~2006	17
TOTAL			30