

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2307	DATE	Feb 5, 2016
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd. )		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2010-2012 MY Cadillac SRX, 2011-2012 MY Chevrolet Camaro vehicles equipped with power height adjustable driver and passenger front seats. Some of these vehicles may have a condition where the bolt that secures the power front seat height adjuster can become loose or fall out. If the bolt falls out, the seat will drop suddenly to the lowest vertical position. The sudden seat movement may affect a driver's ability to safely operate a vehicle or increase the risk of injury to the seat occupant in a vehicle crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「ABA-T166C」	「SRX」	2011	155
「UNKNOWN」	「Camaro」	2011 - 2012	155
		TOTAL	310