

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2337	DATE	2016/6/2
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	Daimler AG has determined that in individual cases on B-Class vehicles (246 platform) with the "Easy-Vario"-option, the bolts connecting the rear seat bench to the body of the vehicle may be missing on one side. In these circumstances, the risk of injury caused by unsecured baggage is potentially increased in case of a frontal crash, where the rear seat bench could potentially be lifted up from the rear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-246242	B180	2013	25
		2014	111
		2015	131
DBA-246244	B250	2013	1
		2014	11
		2015	1
DBA-246246	B250 4MATIC	2015	17
		<b>TOTAL</b>	297