

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2347	DATE	15.07.2016
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	With regards to the inflator of the passenger side airbag module, In the event the airbag is activated, there is a possibility of the failure of the inflator device due to the propellant degradation after long-term exposure to persistent conditions of high humidity, high temperatures, and high temperature cycling. As a result, there is a risk of injury to the passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142	458Italia 458Spider	2010-2011	401
ABA-F149	California	2009-2011	466
ABA-F151	FF	2011	27
		TOTAL	894