

第4号様式 (英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3860	DATE	Aug 26, 2016
MANUFACTURER	Fuji Car Manufacturing Co., Ltd. 13-1 Chishiro-cho, Moriyama-city, Shiga, 524-0034, Japan		
DESCRIPTION OF DEFECT	In terms of the bolt that connects and fixes the tank and the chassis of LPG Bulk-Truck for consumer use, that bolt axial force is insufficient because instruction of the tightening torque for hanger bolt is inappropriate on design. In order to that, the tank swung by the vibration at driving, and the bolt is broken by the excessive stress when continuing to use as it is. In the worst case, there is a possibility that the stability at driving may be impaired.		

MAKER	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Hino	PB-FC6JEFA	Hino Ranger	FC6JEFA-010138~FC6JEFA-010228 20/Apr/2005 ~ 5/Oct/2005	11
	PB-GX7JKFA		GX7JKFA-010023 1/Sep/2005	1
	LD-BZU340M		BZU340-0001112~BZU340-1000041 13/Sep/2005 ~ 29/Aug/2006	4
	PB-FC7JEFA		FC7JEFA-010127 24/Oct/2005	1
	ADG-FC6JEWA		FC6JEWA-010092~FC6JEWA-010315 29/Nov/2005 ~ 4/Dec/2007	23
	PB-XZU331M		XZU331-1000147 11/Apr/2006	1
	PB-XZU334M		XZU334-1000311 26/Sep/2006	1
	ADG-FC7JEWA		FC7JEWA-010575 13/Dec/2006	1
	BDG-XZU334M		XZU334M-1000541 13/Feb/2007	1
	BDG-XZU388M		XZU388M-1000679 27/Jun/2007	1
	NBG-BZU340M		BZU340-1000085 29/Aug/2007	1
	BDG-FC6JEWA		FC6JEWA-010423~FC6JEWA-012129 28/Sep/2007 ~ 12/Oct/2011	39

Hino	BDG-XZU378M	Hino Ranger	XZU378M-1001293 12/Nov/2007	1
	BDG-FC7JEW A		FC7JEW A-010998~FC7JEW A-013065 10/Apr/2008 ~ 13/Oct/2011	6
	BKG-GC7JEY A		GC7JEY A-012003~GC7JEY A-012004 29/Sep/2009 ~ 12/Oct/2010	2
	BDG-GC7JEW A		GC7JEW A-010086~GC7JEW A-012025 17/Nov/2008 ~ 21/Jul/2011	3
	BKG-GC7JJY A		GC7JJY A-010037 28/May/2009	1
	BDG-FX7JGWA		FX7JGWA-012047 28/Jun/2010	1
	SKG-GC7JEAA		GC7JEAA-010016~GC7JEAA-012027 25/Aug/2011 ~ 10/Aug/2012	5
	SKG-FC9 JEAA		FC9JEAA-010040~FC9JEAA-010224 15/Nov/2011 ~ 22/Oct/2012	11
	SDG-FX7JGAA		FX7JGAA-010019~FX7JGAA-010045 22/Dec/2011 ~ 29/Oct/2012	2
	SDG-GX7JKAA		GX7JKAA-010028~GX7JKAA-010122 9/Nov/2012 ~ 5/Nov/2015	6
	TKG-XZU685		XZU685-0001872~XZU685-0004645 21/Sep/2012 ~ 30/Nov/2015	5
	TKG-FC9 JEAA		FC9JEAA-010259~FC9JEAA-011530 4/Oct/2012 ~ 17/Nov/2015	32
	TKG-GC7JJAA		GC7JJAA-010037 2/Nov/2012	1
	TKG-GC7JEAA		GC7JEAA-010068~GC7JEAA-010271 8/Nov/2012 ~ 28/Dec/2015	20
	TKG-XZU640M		XZU640-0001908~XZU640-0003342 1/May/2013 ~ 25/Oct/2014	4
	TKG-XZU685M		XZU685-0002758~XZU685-0004833 18/Nov/2013 ~ 10/Dec/2015	12
	SDG-GX7JGAA		GX7JGAA-011235 2/Oct/2015	1
	TKG-GC7JGAA		GC7JGAA-010293 22/Jan/2016	1
Isuzu	PB-FRR35E3S	Forward	FRR35-7000567~FRR35-7001716 15/Jun/2005 ~ 31/Aug/2007	21
	PB-NRR35E3		NRR35-7000239 11/Aug/2005	1
	PB-NKR81AN		NKR81-7039324 9/May/2006	1

Isuzu	ADG-FRR35G3S	Forward	FRR35-7000205 8/Nov/2006	1
	PB-NKR81N		NKR81-7062853 11/Dec/2006	1
	PB-NKR81N-L		NKR81-7067640 28/Feb/2007	1
	PDG-NKR85YN		NKR85Y-7000177~NKR85Y-7002692 27/Sep/2007 ~ 15/Nov/2011	19
	PKG-FRR90S1		FRR90-7001356~FRR90-7024012 30/Oct/2007 ~ 2/Nov/2011	24
	PKG-FSR90S2		FSR90-7000264 10/Apr/2008	1
	PKG-FRR90S2		FRR90-7007192~FRR90-7015747 13/Jun/2008 ~ 21/Jan/2011	2
	PKG-FSR34S2		FSR34-7001660 1/Feb/2011	1
	SKG-FRR90S1		FRR90-7024020~FRR90-7034378 10/Aug/2011 ~ 26/Jul/2012	4
	SKG-NKR85YN		NKR85Y-7002660~NKR85Y-7004779 10/Nov/2011 ~ 24/Dec/2014	13
	SKG-FSR90S2		FSR90-7002212~FSR90-7003730 31/Oct/2012 ~ 20/Nov/2014	4
	TKG-FRR90S1		FRR90-7044519~FRR90-7086954 28/Mar/2013 ~ 7/Dec/2015	25
	TKG-FRR90S2		FRR90-7043673~FRR90-7078449 13/Mar/2013 ~ 18/Feb/2016	8
	TKG-NKR85AE		NKR85-7031975 25/Nov/2013	1
	TKG-NKR85AN		NKR85-7040673~NKR85-7045573 22/Dec/2014 ~ 5/Jun/2015	2
	TKG-FSR90S2		FSR90-7002794~FSR90-7004582 21/Jun/2013 ~ 28/May/2015	2
SPG-FSR90S2	FSR90-7004681 12/Jun/2015	1		
TKG-NKR85YN	NKR85Y-7005349~NKR85Y-7047123 19/May/2015 ~ 27/Nov/2015	5		
Mitsubishi	PB-FK71RE	Fuso Fighter	FK71RE-775051 14/Nov/2005	1
	PA-FK71DE5		FK71DE-700492~FK71DE-701999 31/May/2006 ~ 27/Mar/2007	5

Mitsubishi	PA-FL63FJX1	Fuso Fighter	FL63FJX-700012 25/Jul/2006	1
	PA-FL63FG1		FL63FG-700049 31/Oct/2006	1
	PA-FK71RE6		FK71RE-701629~FK71RE-702022 9/Nov/2006 ~ 8/Feb/2007	3
	PDG-FK71DE		FK71DE-720973 30/Oct/2008	1
	PDG-FK71RE		FK71RE-720497~FK71RE-721365 10/Jan/2008 ~ 2/Dec/2008	3
	PDG-FK72FE		FK72FE-720128 4/Nov/2008	1
			TOTAL	353

(日本工業規格A列4番)

備考 不具合箇所が複数ある場合であって対象車が異なる場合には、それを区別して記載すること。