

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2377	DATE	2016/9/15
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain E-Class (207, 212 platform) vehicles a lever on the water pump might break. This could lead to a leakage of coolant fluid over time. A leakage of coolant fluid may be contrary to specific Japanese regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-212036C	E250	2014	3,933
RBA-212236C	E250 Wagon	2014	1,685
RBA-207336	E250 Coupe	2014	644
RBA-207436	E250 Cabriolet	2014	318
TOTAL			6,580