

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI – 2932	DATE	Nov 11, 2016
MANUFACTURE	LOTUS CARS Plc (Japanese Importer :LCI Limited)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect fitting an incorrect stop bolt within the brake master cylinder, brake fluid pressure to the front brakes cannot be sufficiently applied if pressure to the rear brake system is lost. Thus the system does not conform to Safety Regulation 12.		

TYPE	COMMERICAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1120	「ELISE」	2016MY	2
-1117-	「ELISE S」	2016MY	4
TOTAL			6