VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2414	DATE	2016/11/30		
MANUFACTURE	Daimler AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT	Daimler AG, after consultation with the Japanese Ministry of Land, Infrastructure, Transport and Tourism (MLIT), has now decided, as a precautionary measure, to also recall potentially affected models of Mercedes-Benz cars in Japan and replace the inflators in a similar procedure based on a graduated scheme. The models affected by this measure in Japan are various Mercedes-Benz cars equipped with Takata PSPI-2 passenger side airbag inflators. We are not aware of any cases worldwide in which our models demonstrate the fault symptoms described by Takata in relation to Takata airbag inflators.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-204046	C180 Compressor	2008	2
DBA-204246	C180 Compressor Wagon	2008	2
DBA-204041	C200 Compressor	2008	10,786
		2009	5,435
		2010	1,601
DBA-204048	C200CGI	2010	327
	C200 Compressor Wagon	2008	1,030
DBA-204241		2009	2,656
		2010	1,104
DBA-204248	C200CGI Wagon	2010	84
DDA 2040E2	C250	2008	3,340
DBA-204052		2009	1,460
DBA-204047	C250CGI	2010	301
DDA 004050	C250 Wagon	2008	425
DBA-204252		2009	757
DBA-204247	C250CGI Wagon	2010	191
DBA-204054	C300	2008	1,400
		2009	408
		2010	305

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-204254	C300 Wagon	2010	93
CBA-204077	C63	2008	203
		2009	767
		2010	296
CBA-204277	C63 Wagon	2008	31
		2009	154
		2010	85
-204008-	C220 CDI	2009	1
-204077-	C63	2008	1
DBA-207347	E250CGI Coupe	2010	554
DBA-207356	E350 Coupe	2010	902
CBA-207372	E550 Coupe	2010	92
DBA-207456	E350 Cabriolet	2010	11
CBA-204981	GLK300 4MATIC	2009	388
		2010	274
ABA-197377	SLS AMG	2011	1
		TOTAL	35,467