VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestie / Import Vehicles

CAMPAIGN No.	Gai-2417	DATE	December 21, 2016
MANUFACTURER	KTM Sportmotorcycle GmbH		
	(Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Market monitoring has shown us that there can be problems with the main wiring		
	harness and ABS system. The main wiring harness contacts wit ABS modulator		
	and it would be tone. It can lead to create an electrical connection via the		
	brake line between the ABS modulator and the vehicle ground. In worst case, ECU which controls ABS system can be caused damage which can result in		
	failure of a brake sys	tem circuit.	

TYPE	COMMEDICAL NAME	MODEL YEAR RECALLED	NUMBER OF
TIPE	COMMERCIAL NAME		VEHICLES
1190ADVV1949	「1190 ADVENTURE 」	From 2013 to 2016	356 UNITS
1190ADVV2949	「1190 ADVENTURE R」	From 2013 to 2016	126 UNITS
1290ADVV5949	「1290 SUPER ADVENTURE」	From 2015 to 2016	84 UNITS
		TOTAL	566 UNITS