

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2431	DATE	February 3, 2017
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a supplier's manufacturing error, there is a possibility that airbags were installed with incorrect ignition units. In the event of accidents in which the restraint systems are triggered, their full protective effect may be impaired as a result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-982H1	718 Boxster	2017	3
ABA-991H1	911 Carrera		3
	911 Carrera S		1
		TOTAL	7