

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2464	DATE	2017/3/30
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	It is possible that ECO start/stop restarts the engine in HOLD mode due to external parameters. The accelerator pedal may interpret the pulse during starting as a start request by mistake, release the HOLD function and the vehicle may slowly start to move. This does not have any effect on the driving or braking behavior.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-447811	V220d	2016	1,327
LDA-447815			213
		TOTAL	1,540