

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2463	DATE	2017/3/30
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain AMG GT (190 platform), C-Class (205 platform) and G-Class (463 platform) vehicles with 8-cylinder gasoline engine (M176, M177, M178) may be equipped with faulty ignition coils. Vibration and temperature influence during driving operation can break faulty soldering points and lead to misfires. In case of failure the malfunction indicator lamp (MIL) would be activated and the respective cylinder could be turned-off. As a consequence, the emission value limits might be exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-190377	AMG GT	2016	90
CBA-190378	AMG GT S	2015	212
		2016	131
CBA-205086	AMG C63	2015	2
		2016	44
CBA-205087	AMG C63 S	2015	312
		2016	224
CBA-205286	AMG C63 Wagon	2015	1
		2016	32
CBA-205287	AMG C63 S Wagon	2015	52
		2016	69
ABA-463234	G550	2016	4
		<b>TOTAL</b>	<b>1,173</b>