## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic /Import Vehicles

CAMPAIGN No.	Gai-2432	DATE	30/March/2017		
MANUFACTURER	Automobiles Volvo Car Corporation				
	(Japanese Importer: Volvo Car Japan Limited)				
DESCRIPTION OF DEFECT	The fuel filter surface material may not withstand the exposure to corrosive environmental conditions, due to insufficient				
	protective layer.				
	The corrective action is to replace the New improved fuel filter				
	with powder coating.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
V0LV0	[V40]	2016		2342
	[V40CC]	2016		926
			TOTAL	3268