

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2428	DATE	30/March/2017
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	The generate mix ratio may in some initiators be out of specification; this could result in a non-deployment of one or more of the affected airbag units in the event of a crash. The corrective action is to replace the regular parts		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S60]	2017	8
	[V60]	2017	74
	[XC60]	2017	46
	[V60CC]	2017	15
	[XC90]	2017	8
	[V40]	2017	196
	[V40CC]	2017	62
		TOTAL	409