VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	GAI-2444	DATE	21 Apr, 2017
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	Driving slowly, engine under-rev in idle, can cause gearbox shift to N or possible engine shut off due to engine software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MLE30E	「Levante S」	2017	140
ABA-MLE30D	「Levante」	2017	86
		TOTAL	226