

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2468	DATE	April 7, 2017
MANUFACTURER	Indian Motorcycle Company (Japanese Importer: White House Automobile Co., Ltd.)		
DESCRIPTION OF DEFECT	Indian Motorcycle has identified a concern on 2014-2017 (Chief Classic, Chief Darkhorse, Chief Vintage, Chieftain, Chieftain Darkhorse, Springfield, Roadmaster) models where the fuel rail can contact other components and cause a fuel leak. A fuel leak in the presence of an ignition source may pose a fire hazard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CCV	Chief Vintage	2014 - 2017	56
CCC	Chief Classic		19
D	Chief Dark Horse		1
CCD	Chief Dark Horse		9
THA	Springfield		1
TCA	Chieftain		35
TCA	Chieftain Dark Horse		2
TRA	Roadmaster		20
			TOTAL