

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

Campaign No.	4051	Date	May 30, 2017
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A flasher blink speed may be slow. Then, it brings non conformance against article 41st.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-H77	「907M」	2015-2016	238
WDP-AY4	「910K」	2015-2016	588
WDP-CD2	「914K」	2015-2016	37
		TOTAL	863