

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

Campaign No.	4050	Date	May 30, 2017
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Hydlauric oil leaks on a steering and implement line due to inappropriate assembly procedure modification. Then, it brings hydlauric oil and steering function lost.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YKYL	「901C2」	2016 - 2017	264
YDM-YKTL	「902C2」	2016 - 2017	175
YDM-YKLL	「903C2」	2016 - 2017	93
		TOTAL	532