

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4049	DATE	Jun 1, 2017
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>On an owner's manual of vehicle, since "installation suitability table of i-Size child restraint system according to seat position" is not indicated, it does not comply with the Safety Regulation Section 22-3.30 (Regulation No. 16, 06 series of amendments) .</p> <p>It does not affect any function when a child restraint system is fixed on a vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-FF21S	IGNIS	2016~2017	30,250
		TOTAL	30,250