

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2495	DATE	2017/6/15
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain A-/B-/E-Class (176/246/213 platform) and GLA/CLA (156/117 platform) vehicles the propellant mix ratio in certain airbag igniters might not meet the specifications, ex works of the supplier. Faulty igniters may lead to improper deployments in situations where the passenger frontal airbag, the kneebag or the window airbag is being activated in case of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-176042	A 180	2017	26
DBA-176051	A250 4MATIC	2017	1
CBA-176052	AMG A45 4MATIC	2017	7
DBA-246242	B 180	2017	45
DBA-117342	CLA 180	2017	72
DBA-117942	CLA 180 SB	2017	61
DBA-117351	CLA250 4MATIC	2017	25
DBA-117951	CLA250 4MATIC SB	2017	7
CBA-117352	AMG CLA45 4M	2017	6
CBA-117952	AMG CLA45 4M SB	2017	4
DBA-156942	GLA 180	2017	13
DBA-156946	GLA250 4MATIC	2017	1
RBA-213271	E400 4MATIC Wagon	2017	1
CBA-213064	AMG E43 4MATIC	2017	11
TOTAL			280