Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

| Campaign No. | Gai- 2514 | Date | July 28, 2017 | | |
|-----------------------|---|------|---------------|--|--|
| Manufacturer | Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited) | | | | |
| Description of defect | From 2009 to 2012 Model Year Jaguar 「XF」 vehicles fitted with a Takata manufactured non-desiccated ammonium nitrate inflator in the Passenger Airbag Module. There have been no reported accidents, injuries or fires as a result of this concern. | | | | |

| Туре | Commercial name | Model year recalled | | Number of vehicles |
|-----------|------------------------------|---------------------|-------|--------------------|
| CBA-J05FA | 「XF Prm. Lux. 3.0 V6」 | 2009-2012 | | 2292 |
| CBA-J051A | 「XF Super V8」 | 2009 | | 126 |
| CBA-J05HA | 「XF Prem. Lux. 4.2 V8」 | 2009 | | 110 |
| CBA-J05LB | 「XF Prem. Lux」 「XF Port.」 | 2010-2012 | | 62 |
| CBA-J05MB | 「XFR」 | 2010-2012 | | 80 |
| | | | Total | 2,670 |