## Vehicle Safety/Pollution Recall Campaign in Japan

## Import Vehicles

Campaign No.	Gai- 2515	Date	July 28, 2017		
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )				
Description of defect	From 2007 to 2012 Model Year Land Rover 「Range Rover」 vehicles fitted with a Takata manufactured non-desiccated ammonium nitrate inflator in the Passenger Airbag Module.  There have been no reported accidents, injuries or fires as a result				
	of this concern.	ported accidents, injune	s or lires as a result		

Туре	Commercial name	Model year recalled		Number of vehicles
ABA-LM42S	「Range Rover」	2007-2009		115
ABA-LM44	「Range Rover」	2007-2009		194
ABA-LM5N	「Range Rover」	2010-2012		285
ABA-LM5S	「Range Rover」	2010-2012		112
			Total	706