

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2517	DATE	Jul 28 <sup>th</sup> , 2017
MANUFACTURE	PIAGGIO & C.s.p.a (Japanese Importer : PIAGGIO Group Japan Corporation )		
DESCRIPTION OF DEFECT	In the braking device, because the wiring of the ABS front brake pipe is inappropriate, due to engine vibration or the like, the pipe may come contact with the secondary air introduction device and be damaged. Therefore, if the owner of the vehicle keeps using it as it is, the brake fluid may leak from the damaged part of the pipe, and in the worst case the front brake may become ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZGULH	「Moto Guzzi V9 Bobber/V9 Roamer」	2016,2017	71 units
		TOTAL	50 units