

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2527	DATE	2017/8/31
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain GLE/GLS (166 platform) and GLE coupe (292 platform) vehicles a connector on the electric power steering might be insufficiently sealed against water entry. In case of an insufficiently sealed connector, moisture might ingress into the control unit of the electric power steering. In this case, the signal transmission inside the control unit might be disturbed and subsequently the steering power assist would be deactivated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-166024	GLE350d 4MATIC SUV	2016	429
	GLE350d 4MATIC Coupe	2016	15
		2017	1
CBA-166064	AMG GLE 43 SUV	2016	116
		2017	1
	AMG GLE 43 Coupe	2016	15
CBA-166074	AMG GLE 63 S	2016	35
	AMG GLE 63 S Coupe	2016	7
LDA-166824	GL350 BlueTEC 4MATIC SUV	2016	789
CBA-166873	GL550 4MATIC SUV	2016	97
	GLS550 4MATIC SUV	2017	1
CBA-166874	AMG GL 63 SUV	2016	3
	AMG GLS 63 SUV	2016	48
		TOTAL	1,557