

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 1 0 3	DATE	Sep.7.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In PTC heater of air conditioning unit, due to the inappropriate fixing of electrical wiring, it is shaken by the vibration etc. while the driving, the terminals might be worn. Therefore if the vehicle continues to be driven in this condition, the interterminal resistance is increased and it generates heat abnormally and smoke might be generated. In an extreme case, it may lead to a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LDA-DNT31	X-TRAIL	2008~2015	26,912
		TOTAL	26,912