

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic)/ Import Vehicles

CAMPAIGN No.	4114	DATE	Sep. 27. 2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain engines of medium duty trucks and buses, due to the improper installation requirement of the wrist pin bushing into the connecting rod, there are some that retention of the wrist pin bushing is insufficient. Therefore, if the vehicle remains in operation with the condition, the wrist pin bushing may wear out and be damaged, causing it to make an abnormal noise, and in the worst case, the engine may be damaged, resulting the vehicle unable to move.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FC7JCWA	[HINO Ranger]	2010～2011	32
BKG-FC7JCYA		2010～2011	600
BDG-FC7JDWA		2010～2011	57
BDG-FC7JEWA		2010	42
BKG-FC7JEYA		2010～2011	155
BDG-FC7JGWA		2010	5
BDG-FC7JGWG			
BKG-FC7JGYA		2010～2011	145
BKG-FC7JGYG			
BKG-FC7JHYA		2010～2011	175
BKG-FC7JHYG			
BDG-FC7JJWG		2010	6
BKG-FC7JJYA		2010～2011	622
BKG-FC7JJYG			
BDG-FC7JKWA		2010～2011	8
BDG-FC7JKWG			
BKG-FC7JKYA		2010～2011	970
BKG-FC7JKYG			
BKG-FC7JLYA		2010～2011	82
BKG-FC7JLYG			
BDG-FC7JNWA		2010	2
BKG-FC7JNYA		2010～2011	62
BKG-FC7JNYG			
BKG-FC7JSYA		2010	5
BKG-FC7JWYA		2010	6
BKG-FC7JWYG			
BDG-FD7JDWA		2010～2011	23
BKG-FD7JDYA		2010	63

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FD7JEWA	[HINO Ranger]	2010～2011	83
BDG-FD7JGWA		2010～2011	63
BKG-FD7JGYA		2010～2011	115
BDG-FD7JJWA		2010	3
BDG-FD7JJWG		2010～2011	106
BKG-FD7JJYA		2010～2011	211
BKG-FD7JJYG		2010～2011	1,263
BKG-FD7JKYA		2010	7
BKG-FD7JKYG		2010～2011	103
BKG-FD7JKYJ		2010～2011	2
BDG-FD7JLWA		2010～2011	120
BDG-FD7JLWG		2010	18
BKG-FD7JLYA		2010～2011	7
BKG-FD7JLYG		2010	17
BKG-FD7JMYA		2010～2011	51
BKG-FD7JMYG		2010	148
BKG-FD7JMYJ		2010～2011	721
BDG-FD7JPWA		2010～2011	119
BDG-FD7JPWG		2010	106
BDG-FD7JPWJ			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FD8JUWA	[HINO Ranger]	2010	98
BDG-FD8JUWG			
BDG-FD8JWWA		2010	5
LDG-FE7JEAA		2010	21
BDG-FE7JEWA		2010	8
LDG-FE7JGAA		2010~2011	39
LKG-FE7JGAA			
BDG-FE7JGWA		2010	27
LKG-FE7JJAA		2010	15
BDG-FE7JJWA		2010	3
LKG-FE7JKAA		2010	33
LKG-FE7JKAG			
BDG-FE7JKWA		2010	14
BDG-FE7JKWG			
LKG-FE7JLAA		2010~2011	105
LKG-FE7JLAG			
BDG-FE7JLWA		2010	48
BDG-FE7JLWG			
LKG-FE7JMAA		2010~2011	85
LKG-FE7JMAG			
BDG-FE7JMWA		2010	13
BDG-FE7JMWG			
LKG-FE7JPAA		2010~2011	103
LKG-FE7JPAG			
BDG-FE7JPWA		2010	14
BDG-FE7JPWG			
LKG-FE7JUAA		2010	10
LKG-FE7JUAG			
BDG-FE8JGWA		2010	11
BDG-FE8JJWA		2010	14
BDG-FE8JKWA		2010	13
BDG-FE8JKWG			
BDG-FE8JLWA		2010	68
BDG-FE8JLWG			
BDG-FE8JMWA		2010	60
BDG-FE8JMWG			
BDG-FE8JPWA		2010	77
BDG-FE8JPWG			
BDG-FE8JUWA		2010	20
LDG-FG8JGAA		2010~2011	7

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FG8JGWA	[HINO Ranger]	2010	4
LDG-FG8JJAA		2010	2
BDG-FG8JJWA		2010	1
LDG-FG8JKAA		2010	16
BDG-FG8JKWA		2010	4
LDG-FG8JMAA		2010~2011	11
BDG-FG8JMWA		2010	8
LDG-FG8JPAA		2010	9
BDG-FG8JPWA		2010	15
LDG-FG8JUAA		2010	2
BDG-FG8JUWA		2010	8
LDG-FG8JWAA		2010	1
LDG-FJ7JDAA		2010	25
BDG-FJ7JDWA		2010	35
LDG-FJ7JEAA		2010	14
LKG-FJ7JEAA			
BDG-FJ7JEWA		2010	8
LKG-FJ7JGAA		2010	11
BDG-FJ7JGWA		2010	10
LKG-FJ7JHAA		2010	5
BDG-FJ7JHWA		2010	6
LKG-FJ7JJAA		2010	15
LKG-FJ7JJAG			
BDG-FJ7JJWA		2010	7
BDG-FJ7JJWG			
LKG-FJ7JKAA		2010~2011	16
LKG-FJ7JKAG			
BDG-FJ7JKWA		2010	26
BDG-FJ7JKWG			
LKG-FJ7JLAA		2010	19
LKG-FJ7JLAG			
BDG-FJ7JLWA		2010	18
BDG-FJ7JLWG			
LKG-FJ7JNAA		2010	16
BDG-FJ7JNWA		2010	10
LKG-FJ7JSAA		2010	3
BDG-FJ7JSWA		2010	3
BDG-FX7JDWA		2010	10
BDG-FX7JGWA		2010	13
BDG-FX7JJWA		2010	12

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FX7JKWA	[HINO Ranger]	2010	1
BDG-FX7JLWA		2010	6
BDG-GC7JCWA		2010	1
BDG-GC7JDWA		2010	4
BKG-GC7JDYA		2010	18
BDG-GC7JEWA		2010	13
BKG-GC7JEYA		2010	22
BKG-GC7JGYA		2010	17
BKG-GC7JHYA		2010	9
BKG-GC7JHYG			
BKG-GC7JJYA		2010	7
BKG-GC7JJYG			
BKG-GC7JKYA		2010～2011	39
BKG-GC7JKYB			
BKG-GC7JKYG			
BKG-GC7JLYA		2010～2011	21
BKG-GC7JLYG			
BKG-GC7JNYA		2010	12
BKG-GC7JSYA		2010	1
BKG-GD7JEYA		2010	11
BDG-GD7JGWA		2010	59
BKG-GD7JGYA		2010	32
BKG-GD7JJYA		2010	24
BKG-GD7JKYA		2010	39
BKG-GD7JKYG			
BKG-GD7JLYA		2010～2011	51
BKG-GD7JLYB			
BKG-GD7JLYG			
BKG-GD7JMYA		2010～2011	11
BKG-GD7JMYB			
BKG-GD7JMYG			
BKG-GD7JPYA		2010	7
BDG-GD8JGWA		2010	6
BDG-GD8JJWA		2010	9
BDG-GD8JJWG			
BDG-GD8JKWA		2010	4
BDG-GD8JLWA		2010	21
BDG-GD8JLWG			
BDG-GD8JMWA		2010～2011	14
BDG-GD8JMWG			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-GD8JPWA	[HINO Ranger]	2010	19
BDG-GD8JPWG			
BDG-GD8JUWA		2010～2011	3
LDG-GK8JKAA		2010	6
BDG-GK8JKWA		2010	30
LDG-GK8JLAA		2010～2011	15
BDG-GK8JLWA		2010	17
LDG-GK8JNAA		2010～2011	21
BDG-GK8JNWA		2010	11
LDG-GK8JRAA		2010～2011	26
BDG-GK8JRWA		2010	20
LDG-GK8JUAA		2010	4
BDG-GK8JUWA		2010	5
LDG-GK8JWAA		2010	17
BDG-GK8JWWA		2010	9
BDG-GK8JWXA		2010	11
BDG-GX7JDWA		2010	5
BDG-GX7JGWA		2010	125
BDG-GX7JKWA		2010	11
BDG-GX7JLWA		2010	3
BJG-HU8JLFP	[HINO Blue Ribbon City]	2010	16
LJG-HU8JLGP		2010～2011	34
BJG-HU8JMFP		2010	25
LJG-HU8JMGP		2010～2011	16
BDG-RU8JHAA	[HINO SELEGA]	2010	34
LDG-RU8JHBA		2010～2011	24
SDG-RU8JHBA			
BDG-HR7JPBE	[HINO Rainbow]	2010	5
BDG-RR7JJBA	[HINO Melpa]	2010～2011	232
		TOTAL	8,802

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FC7JCYA	[HINO Ranger]	2011	1
BKG-FC7JGYA		2008	1
ADG-FC7JHWA		2005	1
ADG-FC7JJWA		2005～2007	3
BDG-FC7JJWA			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FC7JJYA	[HINO Ranger]	2008	3
ADG-FC7JKWA		2006～2007	5
ADG-FC7JKWG			
BDG-FC7JKWA			
BDG-FC7JKWG			
BKG-FC7JKYA		2008～2011	6
BKG-FC7JKYG			
BDG-FC7JLWG		2007	1
BKG-FC7JLYA		2009	1
BKG-FC7JNYA		2008	1
ADG-FD7JDWA		2006	1
ADG-FD7JGWA		2006	2
BDG-FD7JGWA			
BDG-FD7JJWA		2007	1
ADG-FD7JKWA		2005～2007	5
ADG-FD7JKWG			
BDG-FD7JKWA			
BKG-FD7JKYA		2009	2
BKG-FD7JKYG			
ADG-FD7JLWA		2005～2007	23
ADG-FD7JLWG			
BDG-FD7JLWA			
BDG-FD7JLWG			
BKG-FD7JLYA		2008～2011	7
BKG-FD7JLYG			
ADG-FD7JMWG		2005～2007	2
BDG-FD7JMWA			
BKG-FD7JMYA		2009	2
ADG-FD7JPWA		2006～2007	2
BDG-FD7JPWA			
BKG-FD7JPYA		2008	3
BDG-FD8JJWA		2006～2011	2
BDG-FD8JJWG			
PB-FD8JLFG		2005	1
ADG-FD8JLWA		2006～2008	9
ADG-FD8JLWG			
BDG-FD8JLWA			
BDG-FD8JLWG			
BDG-FD8JMWA		2007	1
BDG-FD8JPWA		2007	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-FD8JUFG	[HINO Ranger]	2005	1
BDG-FD8JUWA		2008	1
LKG-FE7JEAA		2012	1
ADG-FE7JJWA		2005～2007	4
BDG-FE7JJWA		2005～2007	6
ADG-FE7JLWA		2007	1
ADG-FE7JLWG		2006	1
BDG-FE7JLWA		2005～2007	6
BDG-FE7JMWA		2006	1
ADG-FE7JPWA		2006～2007	2
ADG-FE8JLWA		2006	1
BDG-FE8JLWA		2006～2007	2
BDG-FE8JLWG		2007	1
ADG-FE8JPWA		2006～2007	2
BDG-FE8JPWG		2005	1
ADG-FE8JUWA		2006	1
ADG-FG8JPWA		2011	1
BDG-FG8JPWA		2005	1
LKG-FJ7JDAA		2007	1
ADG-FJ7JDWA		2005	1
BDG-FJ7JLWA		2006	1
BDG-FX7JJWA		2007	1
ADG-FX7JKWA		2005	1
ADG-GC7JDWA		2009	1
BDG-GD7JGWA		2009	1
BKG-GD7JGYA		2006	1
BDG-GD7JJWA		2007	1
BDG-GD8JMWG		2013	1
LDG-GK8JKAA		2006	1
ADG-GK8JKWA		2009	1
BDG-GK8JLWA		2007	4
BDG-GK8JNWA		2005	1
ADG-GK8JRWA		2006	1
ADG-GK8JUWA		2007	1
BDG-GK8JWWA		2005～2008	4
ADG-GK8JWXA		2007	1
BDG-GK8JWXA			
BDG-GX7JDWA			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-HU8JLFP	[HINO Blue Ribbon City]	2008	1
LJG-HU8JLGP		2012	1
ADG-RU8JHAA BDG-RU8JHAA	[HINO SELEGA]	2006～2008	2
PK-HR7JPAE	[HINO Rainbow]	2004	1
KK-RR1JJGA		2000	1
PB-RR7JJAA	[HINO Melpha]	2005～2006	2
BDG-RR7JJBA		2007～2009	3
		TOTAL	150

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Connecting rod	13260-E0100	2010～2011	80
		TOTAL	80