

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2540	DATE	2017/9/28
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain GLK vehicles (204 platform) with 3.5l Otto -engine M276, the software of the engine control unit may not meet the specifications. The insufficient consideration of fluctuations in the quality-level of the installed NOx sensors could lead to increased NOx emissions.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-204988	GLK350 4MATIC	2013	742
		2014	618
		2015	474
-204988-		2012	1
		<b>TOTAL</b>	<b>1,835</b>